

KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00215	OWNER'S NAME:	WEST
DATE:	1/20/2016	TYPE:	Re-inspection
TIME STARTED:	9:44 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0517		

1. Corrections 2, 3, 5, 10, 13 from previous complete		
2. Gas still not on test. Still at 9#		
3. Panel edge blocking removed at master bedroom P1-2 shearwall		
4. HD9B hold downs not installed in master bed. There does not appear to be signs of straps		
on exterior sheathing		
5. Hold downs in stud in dining slider area need to attach to full height posts per		
manufacturer. Obtain engineer fix or approval for existing attachment to studs under beam		
and stitch nailing requirements		
6. Clarify truss heel to girder connection at master bed IO1, J07 trusses		
7. Remaing previous corrections not yet addressed		

INSTRUCTIONS: Complete current and remaining previous corrections. Obtain engineer corrections where necessary

NEXT INSPECTION: re-inspect framing

RE-INSPECTION FEE DUE?

YES

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

iessica.contratto @co.kittitas.wa.us

\$

• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506