## **INSPECTION REPORT**

IIII ECHOR KEI OKI			
PERMIT NUMBER:	BP-15-00264	OWNER'S NAME:	MCKIM
DATE:	8/5/2016	TYPE:	Insulation
TIME STARTED:	9:39 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-23052-0002		
<ol> <li>Fire separation in garage requires 5/8" type X gypsum board on ceiling. Keep tight to logs and use fire caulk to seal all gaps to logs. Logs need to be coated with an intumescent coating</li> <li>Complete range and dryer vent. See by final. Call office for information on venting options allowed</li> <li>Insulation ok</li> </ol>			
INSTRUCTIONS: Ok to cover  NEXT INSPECTION: Final			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I ADDRESS: ie	NSPECTOR AT THE FO essica.contratto @	
	עטטוובטט <u> </u>	<del>zooica.coninano</del> @	co.nicilas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506