INSPECTION REPORT

IIII ECHON KEI OKI			
PERMIT NUMBER:	BP-15-00371	OWNER'S NAME:	HART
DATE:	1/29/2016	TYPE:	Framing
TIME STARTED:	12:40 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-22000-0011		
1. Add hanger per truss sheet notes on jack trusses JE02, JE07, JB01 2. Truss bracing missing on A08, A09 trusses. Flat ceiling side 3. Truss bracing B02- B05 4. Interior shear to truss connection ok per engineer detail 5. Will verify fireplace drawing combustion air from attic. Approved by manufacturer 6. Verify exhaust duct insulation at next inspection 7. Kitchen loop vent questioned 8. Engineer letter for outlookers vertical cut through top truss chord INSTRUCTIONS: Ok to insulate, see corrections then			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica contratto @co kittitas wa us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506