## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00399	OWNER'S NAME:	THE PASS LLC
DATE:	10/25/2016	TYPE:	Framing
TIME STARTED:	1:24 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	22-11-04055-0016		
<ol> <li>All Prior Shear, Mechanical and Header Corrections OK.</li> <li>Framing OK. Except Perch Framing Attachment. Perch Not Bearing Per Drawing. Engineer Approval Required. Unit 190</li> <li>NOTE: Double Sided Shear Inspection Required Post Insulation Inspection.</li> <li>NOTE: Confirm Fire Marshall Approval of Sprinklers Prior to Cover.</li> <li>NOTE: Inspection of Gypsum Fire Walls Required Prior to Total Cover.</li> </ol> INSTRUCTIONS: OK to Insulate			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: ieremv.haberman @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506