

Mills SP
3/6/18

RECEIVED
AUG 17 2018
Kittitas Co. GDS

FROM		ANGLE		DIST		NORTH	EAST	TO
PT/PT INVERSE		SA (SW of Ditch)						
*****	START					98487.68711	101139.90446	579
							R/W OLSEN DTCH	
579	INV	S	40 40 51	E	60.00	98442.18593	101179.01510	597
							mills	
597	INV	S	49 19 09	W	53.99	98406.99603	101138.07531	598
							mills	
598	INV	S	0 12 01	E	994.63	97412.37052	101141.55095	599
							mills	
599	INV	N	44 49 08	W	1115.83	98203.86848	100355.03863	1038
							DICKEN PROP COR	
1038	INV	N	0 16 51	E	322.16	98526.02251	100356.61691	586
							R/W OLSEN DTCH	
586	INV	S	65 12 29	E	88.83	98488.77324	100437.26107	585
							R/W OLSEN DTCH	
585	INV	S	81 06 51	E	115.99	98470.85726	100551.85643	584
							R/W OLSEN DTCH	
584	INV	N	69 23 21	E	50.93	98488.78518	100599.52553	583
							R/W OLSEN DTCH	
583	INV	N	76 29 18	E	250.51	98547.31442	100843.09949	582
							R/W OLSEN DTCH	
582	INV	S	81 16 51	E	207.51	98533.79823	101048.20146	581
							R/W OLSEN DTCH	
581	INV	S	69 27 42	E	30.29	98505.47128	101076.56681	580
							R/W OLSEN DTCH	
580	INV	S	74 34 05	E	65.71	98487.68711	101139.90446	579
							R/W OLSEN DTCH	

NO CLOSURE ERROR Area = 551885.11 sq ft 12.86954 ac
FROM ANGLE DIST NORTH EAST TO

FROM		ANGLE		DIST		NORTH	EAST	TO
PT/PT INVERSE		SA (NE of Ditch)						
*****	START					98510.90818	101157.56921	1040
							DICKEN PROP COR	
1040	INV	S	40 41 39	E	66.10	98460.79489	101200.86470	818
							mills	
818	INV	S	49 19 09	W	8.55	98455.22281	101194.18216	819
							mills	
819	INV	N	40 40 51	W	66.09	98505.34470	101151.09977	594
							R/W OLSEN DTCH	
594	INV	N	49 18 21	E	8.53	98510.90818	101157.56921	1040
							DICKEN PROP COR	

NO CLOSURE ERROR Area = 561.47 sq ft 0.01296 ac
FROM ANGLE DIST NORTH EAST TO

FROM		ANGLE		DIST		NORTH	EAST	TO
PT/PT INVERSE		SB (SW of Ditch)						
*****	START					98442.18593	101179.01510	597
							mills	
597	INV	S	40 40 51	E	322.16	98197.91610	101388.97784	1031
							DICKEN PROP COR	
1031	INV	S	0 14 33	W	1030.16	97167.78231	101384.61837	1033
							DICKEN PROP COR	
1033	INV	N	44 49 08	W	344.84	97412.37052	101141.55095	599

NO CLOSURE ERROR FROM

Area = 504.47 sq ft 0.01298 ac

ANGLE DIST NORTH EAST TO

=====

PT/PT INVERSE *SB (SW of Ditch)*

***** START

						98442.18593	101179.01510		597
									mills
597	INV	S	40 40 51	E	322.31	98197.91810	101388.97784		1031
									DICKEN PROP COR
1031	INV	S	0 14 33	W	1030.18	97167.76231	101384.61837		1033
									DICKEN PROP COR
1033	INV	N	44 49 08	W	344.84	97412.37052	101141.55095		599
									mills
599	INV	N	0 12 01	W	994.63	98406.99603	101138.07531		598
									mills
598	INV	N	49 19 09	E	53.99	98442.18593	101179.01510		597
									mills

=====

NO CLOSURE ERROR FROM

Area = 258839.74 sq ft 5.94214 ac

ANGLE DIST NORTH EAST TO

=====

PT/PT INVERSE *SB (NE of Ditch)*

***** START

						98442.18593	101179.01510		597
									mills
818	INV	S	40 41 39	E	289.10	98211.30129	101389.16271		1041
									DICKEN PROP COR
1041	INV	S	0 14 33	W	13.15	98228.44798	101389.10705		1042
									DICKEN PROP COR
1042	INV	N	40 40 51	W	299.04	98455.22281	101194.18216		819
									mills
819	INV	N	49 19 09	E	8.55	98460.79489	101200.66470		818
									mills

=====

NO CLOSURE ERROR FROM

Area = 2523.90 sq ft 0.05794 ac

ANGLE DIST NORTH EAST TO

=====

PT/PT INVERSE

***** START

						98460.79489	101200.66470		818
									mills

=====