

128T INV N 8 29 17 W 686.29 662048.38531 1545184.52900 3034
ROAD RIBBON

=====
NO CLOSURE ERROR Area = 130687.73 sq ft 3.00018 ac 662048.38531 1545184.52900 3034
FROM ANGLE DIST NORTH EAST TO

=====
PT/PT INVERSE
***** START *Total* 661975.01826 1544817.11019 2426
REV LOT COR
2426 INV N 48 34 01 E 150.23 662074.43284 1544929.74256 3036
ROAD RIBBON
3036 INV N 82 49 47 E 117.02 662089.03902 1545045.84625 3035
ROAD RIBBON
3035 INV S 73 39 43 E 144.52 662048.38531 1545184.52900 3034
ROAD RIBBON
3034 INV S 67 39 27 E 229.74 661961.05080 1545397.02328 3033
ROAD RIBBON
3033 INV S 57 12 24 E 63.14 661926.85308 1545450.10104 2417
REV LOT COR
2417 INV S 0 15 23 W 561.21 661365.64606 1545447.59028 2418
REV LOT COR
2418 INV N 88 35 45 W 633.33 661381.16665 1544814.45338 2415
REV LOT COR
2415 INV N 0 15 23 E 593.86 661975.01826 1544817.11019 2426
REV LOT COR

=====
NO CLOSURE ERROR Area = 416584.08 sq ft 9.56345 ac 661975.01826 1544817.11019 2426

2
List: from 3 to 3
3 100067.71854 100005.01667 1510.18 CL MVIEW

END List
FROM ANGLE DIST NORTH EAST TO
***** START 661971.61279 1544853.01407 4307
CL 10 DRIVE

ERROR: Invalid Command: 4308.
4307 INV N 65 29 06 E 55.62 661994.68942 1544903.61579 4308
CL 10 DRIVE
4308 INV N 73 19 37 E 25.07 662001.88256 1544927.63280 4309
CL 10 DRIVE
4309 INV S 75 56 36 E 43.58 661991.29705 1544969.91082 4310
CL 10 DRIVE
4310 INV S 58 35 32 E 287.66 661841.39130 1545215.42050 1980
1980 INV N 58 35 32 W 34.48 661859.35973 1545185.99252 1979
1979 INV N 58 35 32 W 253.18 661991.29705 1544969.91082 4310
CL 10 DRIVE

RECEIVED
JUN 07 2006
KITTITAS COUNTY
CDS

ERROR: Invalid Command: pfn.

FROM	ANGLE	DIST	NORTH	EAST	TO
PT/PT INVERSE					
***** START			661975.01826	1544817.11019	2426
					REV LOT COR
2426 INV	N 48 34 01	E 150.23	662074.43284	1544929.74256	3036
					ROAD RIBBON
3036 INV	N 82 49 47	E 117.02	662089.03902	1545045.84625	3035
					ROAD RIBBON
3035 INV	S 73 39 43	E 144.52	662048.38531	1545184.52900	3034
					ROAD RIBBON
3034 INV	S 8 29 17	E 209.29	661841.39130	1545215.42050	1980
1980 INV	N 58 35 32	W 34.48	661859.35973	1545185.99252	1979
1979 INV	S 30 23 17	W 317.48	661585.49891	1545025.39609	1978
1978 INV	N 88 35 45	W 210.07	661590.64694	1544815.39057	1977
1977 INV	N 0 15 23	E 384.38	661975.01826	1544817.11019	2426
					REV LOT COR

=====
 661975.01826 1544817.11019 2426

NO CLOSURE ERROR Area = 155214.97 sq ft 3.56325 ac
 FROM ANGLE DIST NORTH EAST TO

FROM	ANGLE	DIST	NORTH	EAST	TO
PT/PT INVERSE					
***** START			661590.64694	1544815.39057	1977
1977 INV	S 88 35 45	E 210.07	661585.49891	1545025.39609	1978
1978 INV	N 30 23 17	E 317.48	661859.35973	1545185.99252	1979
1979 INV	S 58 35 32	E 34.48	661841.39130	1545215.42050	1980
1980 INV	S 8 29 17	E 477.00	661369.61147	1545285.82829	1981
1981 INV	N 88 35 45	W 471.52	661381.16665	1544814.45338	2415
					REV LOT COR
2415 INV	N 0 15 23	E 209.48	661590.64694	1544815.39057	1977

=====
 661590.64694 1544815.39057 1977

NO CLOSURE ERROR Area = 130681.38 sq ft 3.00003 ac
 FROM ANGLE DIST NORTH EAST TO

FROM	ANGLE	DIST	NORTH	EAST	TO
PT/PT INVERSE					
***** START			662048.38531	1545184.52900	3034
					ROAD RIBBON
3034 INV	S 67 39 27	E 229.74	661961.05080	1545397.02328	3033
					ROAD LATHE
3033 INV	S 57 12 24	E 63.14	661926.85308	1545450.10104	2417
					REV LOT COR
2417 INV	S 0 15 23	W 561.21	661365.64606	1545447.59028	2418
					REV LOT COR
2418 INV	N 88 35 45	W 161.81	661369.61147	1545285.82829	1981
1981 INV	N 8 29 17	W 686.29	662048.38531	1545184.52900	3034
					ROAD RIBBON

=====
 662048.38531 1545184.52900 3034

NO CLOSURE ERROR Area = 130687.73 sq ft 3.00018 ac
 FROM ANGLE DIST NORTH EAST TO