04/23/2012 03:06:50 PM

201204230058 Page 1 of 7 K CO PROSEC

KITTITAS COUNTY CLAIM FOR DAMAGES

Return to: County Auditor 205 W 5th Ave, Suite 105 Ellensburg, WA 98926

Instructions:

Please read the entire form before completion. Fill out each question as completely as possible, to the best of your ability. Do not hesitate to use the back side of this form if you need more than the space provided. An incomplete response may delay the processing of your claim.

1.	Name (Including spouse, if married): Kaven Mathler
	William Mather
2.	21+ Phone (Home): (509-859-4889) (Work): (509-899-1637-
3.	Address (include former address if at present address for less than 6 months):
	1206 N Water St Ellensburg WA 98926
	1206 N Water St, Ellensburg, WA 98926 Mailing Malling
4.	Date of Incident: 4 19/12
5.	Location of Incident: Ruby St- parking area in front of Rublic
	Library - Ellensburg, With
6.	Describe in detail the defect which caused the injury:
	trailer hitch on city/county boility Vehicle

7.	Describe in narrative form and in detail exactly how the incident occurred:	
	Driver Tammy Shuey backed up the City Country truck	
8.	Catching the trailer hitch on my vehicles from bun She put the vehicle in drive it tore off my bumper. Was claim investigated by a police officer? NO	uper-luhan
	Sheriff State Patrol City Police	
9.	Description of claimant's vehicle: Jeep Cherokee Make 1998 Year	
	Model Grand Cherokee Lin 11th License No. ABR 3519	
10.	Describe what you did after the accident occurred:	
	Shucy immediately come up to me - Said Hwasher fault My insurance Company - who tild me that Tammy needed to Describe the conversations you had, if any, with County personnel during or after the	. Tamry . I called
11.	Tammy Shuey admitted guit (fault) of accident. Sho ex	pressed a fe
12.	Describe the damages or injuries which you sustained as a result of the incident: The front bumper was ripped off my vehicle—bree the turn Signal light & parking running light.	
13.	\$ 615.11 See estimate from	\$ 615.11 120.00" pages for Will mather
14.	How did you identify the County as the party responsible for your damage? Louvey I too I number on Side of Vehicle an Tamming Shully identifying where She Work Wifte Managment.	d Ls-
	lieuse plate# 849036 XMT ^{2 of 3}	attirucia

accident. I gave Tammy my divivers Trains foundly vehicle liverset, insurance policy the claims formed office the Thelped Tammy fill out her city/country accident form. We decided not the call the accident form. We decided not the call the police as no injuries and the roadway was not police as no injuries and the roadway was not postructed. Tammy then returned to work, I called they have home.

Filed for Record 04/23/2011 13:06:50 PM - Kittitas County, WA Auditor 11/204230058 Page 5 of 7

MCINTOSH'S AUTOBODY, INc.

Workfile ID: Federal ID:

c49904ca 91-1872392

305 S Water St, Ellensburg, WA 98926

Phone: (509) 925-3867 FAX: (509) 925-3308

Preliminary Estimate

Customer: Mather, William or Karen

Insured:

Mather, William or Karen

Type of Loss:

Policy #: Date of Loss: Claim #:

Days to Repair:

Point of Impact:

Owner:

Mather, William or Karen

1206 N. Water Ellensburg, WA 98926 (509) 899-1637 Cellular

(509) 859-4889 Cellular

Inspection Location:

MCINTOSH'S AUTOBODY, INC.

305 S Water St Ellensburg, WA 98926

Repair Facility

(509) 925-3867 Day

Insurance Company:

VEHICLE

Year: Make:

Model:

1998

JEEP

GRAND CHEROKEE 4X4

LIMITED

Color: Black Int: Body Style:

Condition:

Production Date:

Engine:

4D UTV 6-4.0L-FI VIN:

1J4GZ78S2WC124436

License:

State:

Mileage In: Mileage Out:

Vehicle Out:

Job #:

4 Wheel Disc Brakes 4 Wheel Drive Air Conditioning

Alarm

Aluminum/Alloy Wheels

AM Radio Anti-Lock Brakes (4)

Automatic Transmission

Bucket Seats Cassette

Clear Coat Paint

Climate Control Console/Storage

Cruise Control Driver Air Bag

Equalizer FM Radio

Fog Lamps Intermittent Wipers

Keyless Entry

Leather Seats

Luggage/Roof Rack Message Center

Overdrive Overhead Console

Passenger Air Bag Power Brakes

Power Driver Seat

Power Locks Power Passenger Seat Power Steering Power Windows

Premium Radio Privacy Glass Rear Defogger

Rear Window Wiper Recline/Lounge Seats

Search/Seek Stereo Tilt Wheel

Preliminary Estimate

Customer: Mather, William or Karen

Vehicle: 1998 JEEP GRAND CHEROKEE 4X4 LIMITED 4D UTV 6-4.0L-FI Black

Line	Operation	Description	Qty	Extended Price \$	Labor	Paint
1 2 * 3	Repl	FRONT BUMPER LKQ bumper assy +25% Add for Clear Coat	1	123.75	0.8	2.4 1.0
4 5 ** 6 *	Repl Repl	FRONT LAMPS A/M CAPA LT Turn signal lamp LKQ LT Fog lamp assy	1 1	34.00 12.50	0.1 <u>0.3</u>	
6 * 7 8 #	кер	MISCELLANEOUS OPERATIONS FLEX ADDITIVE	1	7.00		0.5
9 # 10 #		TINT COLOR HAZARDOUS WASTE SUBTOTALS	1	5.00 182.25	1.2	3.9

ESTIMATE TOTALS

Basis		Rate	Cost \$	
			182.25	
1.2 hrs	@	\$ 53.00 /hr	63.60	
3.9 hrs	@	\$ 53.00 /hr	206.70	
3.9 hrs	@	\$ 30.00 /hr	117.00	
			569.55	
\$ 569. 55	<u> </u>	8.0000 %	45.56	
			615.11	
·			0.00	
, <u></u>			0.00	
	-		615.11	
	1.2 hrs 3.9 hrs 3.9 hrs	1.2 hrs @ 3.9 hrs @ 3.9 hrs @	1.2 hrs @ \$ 53.00 /hr 3.9 hrs @ \$ 53.00 /hr 3.9 hrs @ \$ 30.00 /hr	

This is a Preliminary Estimate.

This Estimate is based on our Inspection and does not cover Additional Parts or Labor which may be required after the work has been started and torn down. After the work has started, worn or damaged parts which are not evident on first inspection may be discovered. Naturally this estimate cannot cover such contingencies.

Additional Changes to the Estimate may be required for the actual repair.

--- Parts Prices subject to Invoice ---

AUTHORIZED AND ACCEPTED: McIntosh's Autobody, Inc is here by authorized to make the above specified repairs. I understand that paymet in FULL will be due upon release of vehicle and hereby grant you &/or employee, permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing &/or inspection. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Filed for Record 04/23/2010 03:06:50 PM - Kittitas County, WA Auditor 101204230058 Page 7 of 7

Preliminary Estimate

Customer: Mather, W	Villiam or Karen
---------------------	------------------

Vehicle: 1998 JEEP GRAND CHEROKEE 4X4 LIMITED 4D UTV 6-4.0L-FI Black

Repair Authorized By:	
Date:	

NOTE: You are required to pay for the costs of the repair prior to taking the vehicle from the premises.

IT IS A CRIME TO KNOWINGLY PROVIDE FALSE, INCOMPLETE, OR MISLEADING INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING THE COMPANY. PENALTIES INCLUDE IMPRISONMENT, FINES, AND DENIAL OF INSURANCE BENEFITS.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DE3WA95, CCC Data Date 4/16/2012, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as AM. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Record. Record parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2012 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:


D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

4/19/2012 12:00:09 PM 302317 Page 3







VEHICLE ACCIDENT

MOGTON COUNTINES FOOL Counties for Counties

1. Get Names and License Numbers

OTHER VEHICLE (#2) Driver The Address LADA, D. WATER ST. Sex E. Driver License No. MATTHEK ST. Date of Birth 1.2.11.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
Address SCR-859-4889 Phone SCR-859-4889 Insurance Co. BILAR RIDIAL Agent Backin City Ellurs busy Make of Car Serp 178-358
Odometer Mileage

VEHICLE NO. MBR.3519

Com/ty P.W. - 84903C

OTHER VEHICLE (#3)

Driver
SexDriver License No
Date of Birth
License Plate NoStateState
Owner
Address
Phone
Insurance Co
AgentClty
Make of Car
Orlometer Mileans

IT IS IMPORTANT TO GET AS MANY WITNESSES AS POSSIBLE

WITNESSES AS POSSIBLE
n A/A
ress
ne Age
Ne ,
lressApparent
ne Age
ice Officer
ige No
Get Names of Witnesses

Apparent Age Male Fel Safety Belt UsedYes Taken to	Address	Name	Safety Belt Used Yes	
Female			No No	

3. Get Names of Injured

other (#2) Frant Bumper popped O.F. I. parking 4225 e	VEHICLE DAMAGE	Streets Ruby St. / 3 55 STspeed: Otherm.p.h. Youridis.m.p.h.	City Ed. Lansburg. L. brave,	Accident Date
•				

4. Get the Details

Vehicle tawed to

Other (#3)

Employee - Driver Tammy Shuey	 	o. Diam a checker.	S S S S S S S S S S S S S S S S S S S	LOCAL CARACTER COL	SI POTH	SIEM CONTRACTOR OF THE	inoá.	In a	11805	IDE	way you	high high	DIAC ines et or or	are stre	on in Section 1975	of the writing of the	one one	esU bioo		() ()	CATHO PRE OUT
Title Scale Attendant 1 Date: 4/9/20/2 Person making out list. Tornny Title Date: 4/19/12 Immediate Supervisor		☐ Darkness - street not lit	☐ Darkness - street lit	☐ Dawn	C Dayaght	· 6	LIGHT	N No defects	C Other	 Loose material on surface 	🗀 Holes, deep ruts, bumps	☐ Defective shoulders	ROAD DEFECTS (Check one or more)		☐ Downhill	. D Uphill	☐ Hillcrest	. \ \ Level		মু Straight road	ROAD CHARACTEK (Check two)
IF YOU HAVE COMPLETED THIS FORM, YOU HAVE ALL THE INFORMATION NEEDED FOR AN ACCURATE REPORT. Obtain additional check lists from	-	Somertarty	□ Fog	☐ Snowing	ri Rajoino	2	WEATHER	No traffic control present	Olher	☐ Officer or flagman	☐ Stop-and-go signal	☐ Stop sign	(Check one or more)		□ Other:	co ley	Snowy	□ Muddy	□ Wet	N DIY	(Check one)
	6. Check These Points		Other improper actions:	No improper driving of parking	Improper parking location	Improper starting from parked position	Disregarded other traffic control	Disregarded stop sign	Disregarded stop-and-go light	☐ ☐ Improper turn	☐ ☐ Failed to give proper signal	☐ ☐ On wrong side of road	☐ ☐ Improper passing	☐ ☐ Fallawed too closely	Did not grant right of way to pedestria	Did not grant right of way to venicle	☐ Exceeded lawful speed	Driving under the influence of intoxical	Oth	ur Ca	(Check one or more for each driver)

	Karen Mather #
	Karen Mather 1 Claims 17-7830
	Policy # 475903609
	Blue Rodge
	Jeep Chévokee 11 Washington
	Jeep Cherokee # Washington Lique # ABR3579
,	
	DLH MATHERES97RM - Washington
	exp 12-4-2012
	Janny's WSDL-shuey+1410mo
· -	