INSPECTION REPORT

PERMIT NUMBER:	BP-08-00578	OWNER'S NAME:	THURGOOD
DATE:	7/28/2014	TYPE:	Shearwalls
TIME STARTED:		INSPECTOR:	Amber Green
MAP NUMBER:	19-16-07050-0034		
Interior Shear OK			
INSTRUCTIONS: OK TO COVER			
NEXT INSPECTION: Fireplace Rough-In			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: amber.green @co.kittitas.wa.us			
INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506