## **INSPECTION REPORT**

PERMIT NUMBER:	BP-08-00578	OWNER'S NAME:	THURGOOD
DATE:	10/20/2014	TYPE:	Stove or fireplace
TIME STARTED:	11:06 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-16-07050-0034		
1. fireplac	ce (2) rough in ok		
2. cut sheetrock back 1" from chimney in bedroom			
INSTRUCTIONS:			
NEXT INSPECTION:	final		
RE-INSPECTION FEE I	DUE? NO YES	<u> </u>	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us  • INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			