



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-08-00875

OWNER'S NAME: STEMLEY

DATE: 9/15/2015

TYPE: Framing and mechanical

TIME STARTED: 12:23 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 22-11-11050-0028

	1. frame bearing wall under stair opening to 2x6. Post down under to basement slab
	2. add trimmers or post down under stair tread framing
	3. trusses ok
	4. mechanical ok
	5. all other framing ok
	6. additional permitting needed for gas piping
	7. gas pipe not on test yet

INSTRUCTIONS: ok to insulate, see corrections then

NEXT INSPECTION: insulation

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506