## **INSPECTION REPORT**

PERMIT NUMBER:	BP-09-00323	OWNER'S NAME:	SNYDER-RODMAN
DATE:	8/28/2014	TYPE:	Foundation walls
TIME STARTED:	9:52 AM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-36040-0006		
1. Why w	here the exterior pads p	oured without i	nspection?
2. There is not detail for the sonotube pier at the exterior footings, provide detail from			
the engir	neer.		
INSTRUCTIONS: Perimeter walls OK TO POUR			
NEXT INSPECTION:			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
	TION REQUEST LINE: <a href="www.co.kitti">www.co.kitti</a> L N. Ruby Street, Suite 2, Ellensburg, V		