## **INSPECTION REPORT**

PERMIT NUMBER: BP-10-00558 OWNER'S NAME: RAYMOND

DATE:	12/9/2015	TYPE:	Exterior shear	
TIME STARTED:	10:01 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:	19-16-24050-0106			
1. Shear o	k			
2. Straps a	across rafters over roof s	heathing verified		
INSTRUCTIONS: C	ok to cover			
NEXT INSPECTION:	plumb/mech			
RE-INSPECTION FEI	E DUE? V NO	YES	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
Q	UESTIONS? PLEASE CONTACT	THE INSPECTOR AT THE FOLLO		
		iessica.contratto @co		
		w.co.kittitas.wa.us/cds/red ensburg, WA 98926 ● Main O	quest.asp or 509-962-7694 ●  office Line: 509-962-7506	
	· · · · · · · · · · · · · · · · · · ·			