INSPECTION REPORT

PERMIT NUMBER:	BP-10-00558	OWNER'S NAME:	CARR
DATE:	6/21/2016	TYPE:	Plumbing
TIME STARTED:	9:18 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-16-24050-0106		
4. Plumbing roug 5. Mechanical O 6. Fireplace roug	#/15 mins - Ok not on 2nd Flr - Fill 2nd Flr gh in Ok k		
NEXT INSPECTION: Framing/Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us