## **INSPECTION REPORT**

PERMIT NUMBER:	BP-11-00593	OWNER'S NAME:	SIEPMANN
DATE:	8/15/2014	TYPE:	Footings
TIME STARTED:		INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-15020-0006		
1. rebar i	n footings ok		
INSTRUCTIONS: ok to pour footings			
NEXT INSPECTION:	wall framing		
RE-INSPECTION FEE	DUE? NO YES	<b>,</b>	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BI	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSP		
		ica.contratto @co.ki	
	<b>TION REQUEST LINE: <u>www.co.kitt</u></b> 1 N. Ruby Street, Suite 2, Ellensburg, \		