INSPECTION REPORT

PERMIT NUMBER:	BP-12-00153	OWNER'S NAME:	ALLRED
DATE:	10/31/2014	TYPE:	Insulation
TIME STARTED:	4:08 PM	INSPECTOR:	Amber Green
MAP NUMBER:	17-17-15010-0014		
1. Range	vent must be smooth wa	all vent pipe.	
2. Gable end A35 clips installed per shear schedule?			
INSTRUCTIONS: Complete #1 and provide view of #2. Call for re-inspection.			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us ■ INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ●			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			