## **INSPECTION REPORT**

PERMIT NUMBER:	BP-12-00234	OWNER'S NAME:	LECLAIR
DATE:	9/24/2014	TYPE:	Re-inspection
TIME STARTED:	11:01 AM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-20058-0115		
1. CO2 d	etector in the vicinity of t	he master bed	room.
2. Address permanently posted.			
INSTRUCTIONS: Complete Above, then Final OK			
NEXT INSPECTION: n/a			
RE-INSPECTION FEE		DAID DDIOD TO COUE	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			