## **INSPECTION REPORT**

PERMIT NUMBER:	BP-12-00449	OWNER'S NAME:	ANDERSON
DATE:	8/1/2014	TYPE:	Final
TIME STARTED:		INSPECTOR:	Amber Green
MAP NUMBER:	20-14-24050-0323		
1. 1. Insi	ulate crawl access door.		
INSTRUCTIONS: Fo	orward blower door test results to	o KCCDS. Final Ol	Κ
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE	ECTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
	amber.green @co.kittitas.wa.us		
	<b>TION REQUEST LINE:</b> <u>www.co.kitt</u> 1 N. Ruby Street, Suite 2, Ellensburg, V		