



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-12-00620 OWNER'S NAME: THOMAN
DATE: 3/27/2015 TYPE: Re-inspection
TIME STARTED: 10:51 AM INSPECTOR: Jessica Contratto
MAP NUMBER: 21-14-09063-0003

	1. fireplace ok
	2. 20 min. rated fire door required at garage to porch
	3. clear away dirt from heat pump to allow defrost water to drain away from unit
	4. provide literature for heat pump having 8.5 HSPF for efficiency per energy credits chosen
	5. was blower door test performed on residence? provide results
	6. other previous corrections ok

INSTRUCTIONS: complete above. provide literature and email pics of completed corrections. Once completed, permit card can be signed off at our office if you bring it in

NEXT INSPECTION:

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jessica.contratto @co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506