INSPECTION REPORT

PERMIT NUMBER:	BP-13-00199	OWNER'S NAME:	PAUL NW INVESTMENTS
DATE:	9/19/2014	TYPE:	Re-inspection
TIME STARTED:	11:43 AM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-19051-0072		
1. Steel header and cement board not installed per installation manual at fireplace.			
2. Clean out debris from behind and on top of the fireplace to maintain clearances.			
INSTRUCTIONS:			
NEXT INSPECTION:			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			