INSPECTION REPORT

PERIVITI NUIVIBER:		BP-13-00219	OWNER'S NAIVIE:	SKINNER	
DATE:		10/29/2014	TYPE:	Final	
TIME STARTED:		9:26 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		18-17-11053-0001			
1.	install	stall cover on light switch at door			
INSTRUCTIONS: final ok					
NEXT INSPECTION: N/A					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
		TION REQUEST LINE: <u>www.co.kitt</u> L N. Ruby Street, Suite 2, Ellensburg, V			