INSPECTION REPORT

PERMIT NUMBER:	BP-13-00352	OWNER'S NAME:	BAILEY
DATE:	7/21/2016	TYPE:	Framing
TIME STARTED:	10:43 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-18000-0027		
 Ridge beam Ok Tempered window @ stairs (film installed) Ok Owner to issue letter for abandoning plumbing Need to determine fireplace clearances NOTE: Dormer framing next inspection INSTRUCTIONS: Complete dormer framing/Provide fireplace clearances			
INSTRUCTIONS: Complete dornier framing/Provide mepiace clearances			
NEXT INSPECTION: Framing/Final			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
OUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING F-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

<u>justin.bennett</u> @co.kittitas.wa.us