



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-13-00408

OWNER'S NAME: BALDOCK

DATE: 8/7/2015

TYPE: Final

TIME STARTED: 1:28 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-14-24051-0613

	1. CO detectors outside sleeping areas
	2. main fireplace in great room not operational
	3. fireplace in media room not operational
	4. All other fireplaces ok
	5. Blower door improved from 6.36 to 5.2-ok per 2009
	6. continuous fan in crawl-ok
	7. media room fireplace not on plans. Added fee for appliance needed
	8. media room fireplace clearances on sides not met
	9. all installed plumbing ok

INSTRUCTIONS: complete above

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jessica.contratto@co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506