INSPECTION REPORT

TYPE:

OWNER'S NAME: J RANDALL

Insulation

PERMIT NUMBER: BP-13-00500

DATE:

10/20/2015

TIME STARTED:		2:14 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		17-19-35054-0003			
	1. Truss bracing ok				
	2. insulation ok				
INSTRUCTIONS: ok to cover					
NEVE	INCOCCTION				
NEXI	INSPECTION:	final			
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
	 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				
411 N. Nuby Street, Suite 2, Eliensburg, WA 30320 Vividin Office Line. 303-302-7300					