## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00512	OWNER'S NAME:	CHURCH
DATE:	12/15/2014	TYPE:	Final
TIME STARTED:	1:10 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0322		
1. CO de	tector required outside b	unkroom	
2. check with fire marshal to see if generator needs permitting			
INSTRUCTIONS: complete above,			
NEXT INSPECTION:	re-final		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:  jessica.contratto @co.kittitas.wa.us			
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ■  411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ■ Main Office Line: 509-962-7506			