INSPECTION REPORT

PERMIT NUMBER:	BP-13-00659	OWNER'S NAME:	REIMER
DATE:	3/20/2015	TYPE:	Exterior shear
TIME STARTED:	3:13 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19051-0080		
1. shear	ok		
2. bottom	nailing on garage kicko	ut	
3. engine	er letter for sill plate		
INSTRUCTIONS: CO	mplete nailing, ok to cover		
NEXT INSPECTION:	frame/plumb/mech		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE	CTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
	jessi	ca.contratto @co.ki	ittitas.wa.us
	TION REQUEST LINE: www.co.kitti 1 N. Ruby Street, Suite 2, Ellensburg, V		