INSPECTION REPORT

TYPE:

BP-13-00707

10/31/2014

PERMIT NUMBER:

DATE:

OWNER'S NAME: WALLACE

Gas piping

TIME STARTED:	2:11 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0032		
1. gas at 15#/15 min-ok			
INSTRUCTIONS:			
NEXT INSPECTION: frame/mech			
RE-INSPECTION FE	EE DUE? NO YES	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			
, , , , , , , , , , , , , , , , , , , ,			