INSPECTION REPORT

PERMIT NUMBER:	BP-13-00707	OWNER'S NAME:	WALLACE
DATE:	12/15/2014	TYPE:	Framing
TIME STARTED:	2:33 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0032		
1. cannot	see RBC clips in guest	closet. send pi	cs
2. bath fan not complete downstairs			
3. trusses	s ok		
INSTRUCTIONS: ok to insulate, send pic of clips			
NEXT INSPECTION: i	nsulation		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
		ca.contratto @co.ki	
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			