## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00707	OWNER'S NAME:	WALLACE
DATE:	1/23/2015	TYPE:	Insulation
TIME STARTED:	11:29 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0032		
1. correct	tions ok		
2. insulat	ion ok		
INSTRUCTIONS: OK	to cover		
NEXT INSPECTION: 1	final		
RE-INSPECTION FEE I	DUE? NO YES	3	\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSP jess	ector at the follow ica.contratto <b>@co.k</b> i	
	TION REQUEST LINE: <a href="www.co.kitt">www.co.kitt</a> L N. Ruby Street, Suite 2, Ellensburg, N		