



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-13-00707

OWNER'S NAME: WALLACE

DATE: 6/23/2015

TYPE: Final

TIME STARTED: 10:54 AM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-14-13050-0032

	1. Complete fire separation in garage
	2. Fireplace Final Ok
	3. Blower door not complete
	4. L&I sign off complete
	5. Mechanical fire separation
	6. Verify hot tub permit
	7. Complete crawl space doors in mechanical room
	8. Smoke/CO Ok
	9. Energy credits Ok
	10. Complete range shroud

INSTRUCTIONS: Complete items above/Re-inspection

NEXT INSPECTION: Re-Inspection

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

justin.bennett@co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506