## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00709	OWNER'S NAME:	COLLIER
DATE:	9/9/2014	TYPE:	Foundation walls
TIME STARTED:	1:41 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-09051-0001		
1. ok to p	our walls		
2. see int	erior pad and rebarbefor	re pouring slab	
3. 24x24	footing pad on east wall	?	
INSTRUCTIONS: OK	to pour walls		
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	<b>TION REQUEST LINE:</b> <a href="www.co.kitt">www.co.kitt</a> 1 N. Ruby Street, Suite 2, Ellensburg, V		