INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-13-00709

11/25/2014

OWNER'S NAME:

COLLIER

Framing

TIME STARTED:		2:03 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		17-18-09051-0001		
1	l. unable to	complete framing inspection (until electrical, plui	mbing and mechanical is comp
I	ete			
INSTRUCTIONS: complete above, call for re-inspection				
NEXT INSPECTION: re-inspection				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				
•				