INSPECTION REPORT

PERMIT NUMBER: BP-13-00709 OWNER'S NAME: COLLIER

DATE:	5/18/2015	TYPE:	Insulation	
TIME STARTED:	10:07 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:	17-18-09051-0001			
1. Floor Insulation Ok				
2. Wall Ins	ulation Ok			
3. Rafter Ir	nsulation Ok			
4. Insulate	hood vent			
INSTRUCTIONS:	nsulate hood vent/Ok to cover	,		
NEVT INCRECTION				
NEXT INSPECTION:	Final			
RE-INSPECTION FEE	E DUE? V NO	YES	\$	
IF REC	QUIRED, RE-INSPECTION FEES MUS	T BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION	
QI	UESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:	
		iustin.bennett @co	o.kittitas.wa.us	
	CTION REQUEST LINE: www.co.			
4	11 N. Ruby Street, Suite 2, Ellensbu	ig, wa 98926 • Iviain (Jilice Lifie: 509-962-7506	