INSPECTION REPORT

OWNER'S NAME: FREED LLC

TYPE:

Mechanical

PERMIT NUMBER: BP-13-00740

DATE:

9/25/2015

TIME STARTED:		12:08 PM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-15-19051-0043			
	1. Gas Line OK. 30#/15min.				
	2. Laundry Room Duct Chase Draftstop Not Complete. Will See at Insulation.				
	3. Fireplace Rough In NotComplete. Draftstop Not Complete. Will See at Insulation.				
INSTR	UCTIONS: (OK to Insulate.			_
					_
NEXT	INSPECTION:	Insulation.			
RE-IN	SPECTION FEI	E DUE? NO	YES	\$	_
	IF RE	QUIRED, RE-INSPECTION FEES MU	ST BE PAID PRIOR TO SCH	HEDULING A RE-INSPECTION	
	Q	UESTIONS? PLEASE CONTACT THE	INSPECTOR AT THE FOLLO	DWING E-MAIL ADDRESS:	
		ie	eremv.haberman @co	.kittitas.wa.us	
		CTION REQUEST LINE: <u>www.co</u> 11 N. Ruby Street, Suite 2, Ellensbu			
	4	TT N. Nuby Street, Suite 2, Ellelisbi	aig, WA 30320 ♥ Widill O	THE LINE. 303-302-7300	