INSPECTION REPORT

PERMIT NUMBER:	BP-13-00811	OWNER'S NAME:	MOON
DATE:	6/30/2015	TYPE:	Insulation
TIME STARTED:	11:47 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-08000-0016		
1. insulation	ok		
2. 1" clearance to chimney from drywall -take pic			
3. metal collar around chimney at draftstop- take pic			
4. passive air inlets needed in habitable rooms			
5. build drywall enclosures for speakers in garage separation, seal all wire penetrations			
6. complete plumbing vents up exterior			
7. complete LVL support corretion in garage area. Living area complete			
INSTRUCTIONS: complete above, ok to cover			
NEXT INSPECTION: final			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			