## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00817	OWNER'S NAME:	MORGAN
DATE:	12/9/2014	TYPE:	Shearwalls
TIME STARTED:	1:25 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-14-34050-0001		
1. downs	tairs framing ok		
2. add circuit for smoke/CO detector in downstairs			
3. interior shear ok			
INSTRUCTIONS: ok to insulate downstairs walls after L&I approval on electrical			
NEXT INSPECTION: framing upstairs			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			