INSPECTION REPORT

PERMIT NUMBER:		BP-14-00040	OWNER'S NAME:	VARNUM	
DATE:		12/11/2014	TYPE:	Final	
TIME STARTED:		1:03 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		17-19-02071-0003			
1. Se	ismi	c straps on water heater	•		
2. blo	2. blower door test to show air changes per hour				
3. insulate ductwork in garage R-8					
4. fire caulk garage ceiling to top plate					
INSTRUCTIONS: complete above, call for re-inspection					
		<u> </u>			
NEXT INSPECTION: re-final					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
jessica.contratto @co.kittitas.wa.us					
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					