## **INSPECTION REPORT**

BP-14-00060

**PERMIT NUMBER:** 

OWNER'S NAME: WHITEHAIR

DATE:		8/8/2014	TYPE:	Exterior shear	
TIME STARTED:		2:30pm	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-15-29051-0099			
1.	1. 4 MSTC28 straps missing at upstairs P1-4				
INSTRUCTIONS: put straps on, send pic. Then ok to cover					
NEXT INSPECTION: frame/plumb/mech					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
jessica.contratto @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					