INSPECTION REPORT

PERMIT NUMBER:	BP-14-00060	OWNER'S NAME:	WHITEHAIR
DATE:	9/16/2014	TYPE:	Framing
TIME STARTED:	3:35 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-29051-0099		
1. Truss b	pracing missing on two tr	usses.	
2. MST strap from beam to studs at great room.			
3. Framing detail for upper floor roof framing provided on site.			
4. Bearing at over framing ridge board.			
5. Fireplace in bedroom to have a minimum of 2 1/2 inches behind.			
6. Seal up draftstop at fireplace.			
7. Gasline (30#/15min) - OK			
8. DWV (H2O/15min) - OK H2O (working pressure) - OK			
INSTRUCTIONS: Complete Above, Re-Inspection			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			