



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00068

OWNER'S NAME: BACK COUNTRY

DATE: 9/9/2014

TYPE: Insulation

TIME STARTED: 11:19 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 19-15-07060-0003

1. strap top plate where cut out above laundry room for heat duct
2. vapor barrier behind exterior side of tubs
3. see floor insulation at final

INSTRUCTIONS: complete above, ok to cover

NEXT INSPECTION: final

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto@co.kittitas.wa.us

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506