INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00078

10/17/2014

OWNER'S NAME:

GORDON

Mono pour

TIME STA	RTED: 10:45 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:			
1. front left 48x48 footing needs (7) #4 bar each way. only has 4			
INSTRUCTIONS: add bar in footing, ok to pour			
NEXT INSPECTION: interior footings			
RE-INSPE	CTION FEE DUE? NO YE	:S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			
,,			