



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00083 **OWNER'S NAME:** DAVIDSON
DATE: 11/4/2014 **TYPE:** Insulation
TIME STARTED: 2:00 PM **INSPECTOR:** Jessica Contratto
MAP NUMBER: 19-17-01000-0005

1. insulation ok

INSTRUCTIONS: ok to cover. fireplace needs inspection before cover after enclosure is framed

NEXT INSPECTION: final/fireplace

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506