## **INSPECTION REPORT**

PERMIT NUMBER:		BP-14-00083	OWNER'S NAME:	DAVIDSON
DATE:		7/13/2015	TYPE:	Multiple (see notes)
TIME STARTED:		2:42 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		19-17-01000-0005		
	1. Plans/F	Permit Not On Site.		
	2. Fireplace Installation Manual Not On Site			
	3. No Record of Passed Gas Line Pressure Test. Gas Line Currently Not On Test.			
	4. Combustion Air Supply to Fireplace Not Complete to Exterior.			
	5. Unclear Whether Fireplace is Solid Fuel Burning. Fireplace Doors Not Present at Time of			
	Inspection.			
INSTRUCTIONS: MAke Corrections Above. Call for ReInspection.				
NEXT INSPECTION: ReInspect				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>				