



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-14-00099

OWNER'S NAME: MARSHALL

DATE: 8/10/2016

TYPE: Final

TIME STARTED: 9:11 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 18-19-35000-0012

1. Seal penetrations in fire separation in water heater alcove wall and at gas pipe for furnace
2. Door from residence to garage to be self closing/latching
3. Blower door test not on site
4. Egress door requires 36" length landing out from door
5. Vented windows required with whole house fan. Whole house ventilation system supplying fresh air to furnace also acceptable
6. Energy credits ok

INSTRUCTIONS: Complete above, re-inspect

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE?  NO  YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506