## **INSPECTION REPORT**

TYPE:

**PERMIT NUMBER:** 

DATE:

BP-14-00135

2/10/2015

OWNER'S NAME: GRANITE CREEK

Insulation

TIME STARTED	: 10:12	AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	19-14	-03000-0086	6	
1. Range Vent Install OK.				
2. Insulation OK.				
3. Corrections OK.				
INSTRUCTIONS: Ok to Cover				
NEXT INSPECTION: Final				
RE-INSPECTION	I FEE DUE?	✓ NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>				
711 W. Mady Street, Saite 2, Eliciobarg, WA 30320 9 Wall Office Line. 303 302 7300				