## **INSPECTION REPORT**

TYPE:

**PERMIT NUMBER:** 

DATE:

BP-14-00166

10/1/2014

OWNER'S NAME:

THE PASS LLC

Re-inspection

TIME STARTE	D: 11:05 AM	INSPECTOR:	Jessica Contratto
MAP NUMBE	r: 22-11-04055-0026		
1. exterior shear ok on side and back			
INSTRUCTIONS: ok to cover exterior on side and back of unit			
NEXT INSPECTION: front shear			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			