INSPECTION REPORT

PERMIT NUMBER:

BP-14-00183

OWNER'S NAME:

BURNSTEAD

DATE:		7/10/2014	TYPE:	Slab plumbing	
TIME STARTED:		12:50 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-15-20059-0029			
	D\\\\\	ata ala ta at			
	DWV on stack test				
	insulatio	ulation OK			
INSTRUCTIONS: ok to pour					
NEXT INSPECTION: floor framing					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					
TIT N. Nuby Street, Suite 2, Literisburg, WA 30320 Viviani Office Line. 303-302-7300					