INSPECTION REPORT

PERIVITI NUIVIBER:	BP-14-00184	OWNER'S NAIVIE:	BEZONA
DATE:	7/30/2014	TYPE:	Mechanical and plumbing
TIME STARTED:		INSPECTOR:	Amber Green
MAP NUMBER:	20-15-29050-0143		
1. Comp	lete exhaust fan ductwo	rk.	
2. Complete and insulate range vent.			
DWV (H2O/15min) - OK			
H2O lines - working pressure			
Gasline (22#/15 min) - OK			
INSTRUCTIONS:			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE	DUE? NO YES	i	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			