INSPECTION REPORT

PERMIT NUMBER:	BP-14-00189	OWNER'S NAME:	NELSON
DATE:	5/6/2015	TYPE:	Final
TIME STARTED:	10:19 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-27020-0031		
1 no record	d of gas nining inspection for add	led nining to applia	nces on new deck
 no record of gas piping inspection for added piping to appliances on new deck. Fire marshal inspected required for fire mitigation 			
3. glass guard panels not installed on deck perimeter			
4. hot tub and cover ok			
5. grippable handrail required at deck stairs exceeding 3 risers			
INSTRUCTIONS: complete above			
NEXT INSPECTION: re-inspect/ fire marshal			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •			