INSPECTION REPORT

PERMIT NUMBER:	BP-14-00236	OWNER'S NAME:	CHILDERS
DATE:	3/13/2015	TYPE:	Final
TIME STARTED:	1:08 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0043		
1. 36" ler	ngth landing at egress do	oors on exterior	•
2. maximum 7.75" from threshold to grade or landing			
3. CO detector needed outside guest bedroom			
4. vent terminations needed on exterior			
5. cover on crawl access outside			
6. exterior not weather proof. Need exterior coverings and caulk or seal building exterior			
envelope			
7. leak at guest bath toilet			
8. fireplace ok			
9. seal around water heater flue pipes, gas valve and range vent			
10. furnace combustion air termination clearance to nearby exhaust terminations			
INSTRUCTIONS: complete above, call for re-inspection			
NEXT INSPECTION: re-inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
■ INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ■			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506