INSPECTION REPORT

PERIVITI NUIVIBE	R: BP-14-00244	OWNER'S NAIVIE:	JACOBSEN
DATE:	10/1/2014	TYPE:	Insulation
TIME STARTED:	2:26 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-02061-0001		
1. Fran	ning ok per Amber		
2. insu	lation ok		
INSTRUCTIONS:	OK to cover		
NEXT INSPECTION	N: final		
RE-INSPECTION F	EE DUE? NO YES	S	\$
	REQUIRED, RE-INSPECTION FEES MUST B		
	QUESTIONS? PLEASE CONTACT THE INSP		
		sica.contratto @co.k	
• INSI	PECTION REQUEST LINE: www.co.kitt 411 N. Ruby Street, Suite 2, Ellensburg, V		